



Figure 1 Bond strength as a function of substrate and coating thickness for HVOF coupons. Note that in all the samples sprayed at 0.040", the failure was in the adhesive, indicating that the bond strength is greater than the values shown.

BEST AVAILABLE COPY